

APPENDIX B

Summary of Lend Lease Compliance at Lamberts North



	September 2018	October 2018	November 2018	December 2018	January 2019	February 2019	March 2019	April 2019	May 2019	June 2019	July 2019	August 2019
Ash Moisture Fresh Water 18-20%	С	С	С	С	С	С	С	С	С	С	С	С
Compaction Testing Dry density ratio 95% Fresh ash acceptable 93%	С	С	С	С	С	С	С	C	С	С	С	С
Landform Stability No slumping or movement	С	С	С	С	С	С	С	C	С	C	С	С
Weather station operational	С	С	С	С	С	С	С	С	С	С	С	С
Irrigation system Operational	С	С	С	С	С	С	С	С	С	С	С	С
Internal dust deposition gauges Insoluble solids = 4 g m ⁻² month	С	С	С	С	С	С	С	С	С	С	С	С
Ash Contaminated Water contained within site boundary	С	С	С	С	С	С	С	С	С	С	С	С
Geotechnical vibrating wire piezometers Stack stability	С	С	С	С	С	С	С	С	С	С	С	С
No Community complaint	С	С	С	С	С	С	С	С	С	С	С	С