

## **Open Cut Summary Rehabilitation Cost Estimation**

Note: Sections of this page	are automatically filled in from the registration page			
Mine Name:	Pine Dale Mine			
Lease(s):	ML 1578, MI 1569, ML 1664 & ML 1637			
Authorisation Owner:	Enhance Place Pty Limited			
Mine Operator:	Enhance Place Pty Limited			
Term of RCE:	1/7/2025			
Current Security:	\$1,112,000 Date of Last Security Deposit Review: 1/07/202			1/07/2022
Mine Contact:	Mark Frewin			
Position:	Coal Supply Lead			
Address:	Level 19, Two Melbourne Quarter 697 Collins Street Docklands VIC 3008			
Phone:	0438 338 176 Email: mark.frewin@energyaustralia.com.au			
	Domain		Security l	Deposit
Domain 1: Infrastructure				\$331,687
Domain 2: Tailings & Re	ejects			
Domain 3: Overburden & Waste				\$177,871
Domain 4: Active Mine & Voids			\$345,285	
Domain 5: Managemen	t Activities			\$113,750
Subtotal (Domains and	d Sundry Items)			\$968,594
Contingency				\$96,859
Post Closure Environmental Monitoring Project Management and Surveying				\$96,859
-roject Management ar	id Surveying	10%		\$96,859
Total Security Deposit for the Mining Project (excl. of GST) \$1,259,172				
Alterations have been The proposed rehabil This Registration Form, \$ This mine security calculati	d in the above calculation or as part of rehabilitation sec a made to unit prices within this spreadsheet. (Attach a sepa- itation design is generally consistent with the development of Summary Report and calculation pages are to be printed ion has been estimated using the best available information dection of the total rehabilitation liability held by this mine.	arate sheet pro consent for the and attached	oviding details of change project.	s).
Mark Frewin Company Resprese	ntative's Name		22/3/20 Date	24
Coal supply lead Company Represent	tative's Role / Responsibility		Signatu	In Francisco