

APPENDIX H

Annual Summary of Lend Lease Compliance at Lamberts North

2017-2018 Annual Summary OF Lend Lease COMPLIANCE AT LAMBERTS NORTH

C: Compliant

NC: Non-compliance

	2017				2018							
	September	October	November	December	January	February	March	April	Мау	June	July	August
Ash Moisture – Fresh Water 18-20%	С	С	С	С	С	С	С	С	С	С	С	С
Compaction Testing Dry density ration 95% Fresh ash acceptable 93%	С	С	С	С	С	С	С	С	С	С	С	С
Landform Stability No slumping or movement	С	С	С	С	С	С	С	С	С	С	С	С
Weather Station Operational	С	С	С	С	С	С	С	С	С	С	С	С
Irrigation system Operational	С	С	С	С	С	С	С	С	С	С	С	С
Internal Dust Deposition Gauges Insoluble Solids = 4gm ⁻²	С	С	С	С	С	С	С	С	С	С	С	С
Ash Contaminated Water Contained within site boundary	С	С	С	С	С	С	С	С	С	С	С	С
Geotechnical vibrating wire piezometers Stack stability	C	С	C	С	С	С	С	С	С	С	С	С
Community Complaint None	С	С	С	С	С	С	С	С	С	С	С	С